



RD CLEAR BASE

Product Information Bulletin

Recommended Parameters

RD CLEAR BASE

It is a water based printing base that has high colour and soft touching effect used by discharging the color of the dischargeable fabric in textile printing. It can be used as a transparent or can be colored with pigments.



Highlights

- ▶ It is a discharge printing products
- ▶ If used correctly as advised, the dry-wet rubbing and washing fastness are high
- ▶ It provides to extremely soft touching effects.
- ▶ Easy using during the print
- ▶ Vivid color and soft handfeel effect
- ▶ Rubbing and washing tests should be applied 24 hours after curing



Printing Tips

- ▶ It used by discharging the color of the dischargeable fabric
- ▶ It is a discharge printing products.



Precautions

- ▶ Never use water to reduce the viscosity.
- ▶ Before usage, please stir the product well. Do not use any additives that are not advised.
- ▶ After using, the screen should be cleaned with water and sponge.
- ▶ Soluble in water.
- ▶ It is packed in 30kg and 60kg blue polyethylene cans.
- ▶ It is advised to mix with RD White
- ▶ The technical application and information that have been given above, are designed only as using instructions. Should not be considered as a warranty for any other use. If any further help or assistance is required, our technical department is ready for help.
- ▶ In case of emergency, Safety Data Sheet of this product should be ready for help at the working area.
- ▶ The warnings available on safety data sheets have been written for the purpose of providing comprehensive information on the products & in case of any nonconforming usage can not be held responsible for any direct and/or indirect loss or damage of the manufacturer/distributor.
- ▶ Email: info@inknovators.com

Mesh

Counts: 43-62 mesh



Squeegee

Durometer: 50-60 Shore
U type dr. blade



Cure Temperatures

320°F(160°C) for 2 minutes



Additives

Do not use any additives that are not advised
5% decroline should be added into the mixture



Shipping & Storage

41°F - 86°F (5°C - 30°C)



Clean Up

Use water to clean



Health & Safety

Please see: Safety Data Sheet



RD CLEAR BASE